

9. Сваи			
C 30-30-6	0,28	3000x300x300	2,550.00
C 40-30-6	0,37	4000x300x300	3 200,00
C 50-30-6	0,46	5000x300x300	4 000,00
C 60-30-8,1	0,55	6000x300x300	5 300,00
C 60-30-6,1	0,55	6000x300x300	4 750,00
C 70-30-8,1	0,64	7000x300x300	6 400,00
C 80-30-8,1	0,73	8000x300x300	7 200,00
C 90-30-6	0,82	9000x300x300	7 350,00
C 90-30-8	0,82	9000x300x300	8 200,00
C 100-30-6	0,91	10000x300x300	8 250,00
C 100-30-8	0,91	10000x300x300	9 200,00
C 110-30-8	1	11000x300x300	10 200,00
C 110-30-9	1	11000x300x300	10 900,00
C 120-30-8	1,09	12000x300x300	11 000,00
C 120-30-9	1,09	12000x300x300	12 000,00
10. Сваи стаканного типа			
C 190.30C	1,72	19000x300x300	19 800,00